

DTIC FILE CORY

MTL TR 87-44

AD



366

# **EVALUATION OF** THIXOCAST CARTRIDGE **STOP PAWLS**

PERRY R. SMOOT

PROCESSING TECHNOLOGY DIVISION

September 1987

Approved for public release; distribution unlimited.





U.S. ARMY MATERIALS TECHNOLOGY LABORATORY Watertown, Massachusetts 02172-0001

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	
MTL TR 87-44	APA 16 366	
4. TITLE (and Subtitle)		5. TYPE OF REPORT & PERIOD COVERED
EVALUATION OF THIXOCAST CARTRIDGE STOP PAWLS		Final Report
		6. PERFORMING ORG, REPORT NUMBER
7. AUTHOR(a)		B. CONTRACT OR GRANT NUMBER(s)
Perry R. Smoot		
refry k. Smoot		
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK
U.S. Army Materials Technology Lal	oratory	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS D/A Project: 1L162105AH84
Watertown, Massachusetts 02172-000	-	AMCMS Code: 62105.H840011
SLCMT-MCD-E		Agency Accession: DAOG 4774
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
U.S. Army Laboratory Command		September 1987
2800 Powder Mill Road		13. NUMBER OF PAGES
Adelphi, Maryland 20783-1145		15
14. MONITORING AGENCY NAME & ADDRESS(II dilleren	t from Controlling Office)	15. SECURITY CLASS. (of this report)
		Unclassified
		154. DECLASSIFICATION/DOWNGRADING SCHEDULE
Approved for public release; dist		
19. KEY WORDS (Continue on reverse side if necessary and	nd identify by block number)	
Casting Steel	casting	
Foundries Die ca	_	
	tructure	j
Billets (materials)		
20. ABSTRACT (Continue on reverse side if necessary en	d identify by block number)	
(SEE	REVERSE SIDE)	

Block No. 20

# **ABSTRACT**

The objective of this work was to evaluate thixocast cartridge stop pawls for the M85 machine gun in accordance with applicable specifications. A "lot" composed of eight pawls was evaluated and found satisfactory with respect to chemical analysis. However, radiography revealed sponge and centerline shrink. Magnetic particle and visual inspection revealed severe surface cracking. Metallography showed hot tears, gas porosity, cold shots, inclusions, and gross chemical segregation, resulting in microstructural variation from ferrite to martensite, and hardness variation from 26 to 59 HRC. This segregation persisted through heat treatment. The surface hardness, roughness, and dimension did not conform to specifications, and the castings did not fulfill the specifications. The above defect problems must be resolved before the process can be utilized.

Acces	ssion For
NTIS	GRA&I
DTIC	TAB (1)
Unanr	nounced 🔲
Justi	fication
By Distr	ibution/
Avai	lability Codes
Dist	Avail and/or Special
A-1	
	(NSTY)

#### **BACKGROUND**

# Massachusetts Institute of Technology Work

MTL awarded a contract to the Massachusetts Institute of Technology to investigate the "thixocasting" process. Thixocasting is a casting process in which a previously "rheocast" metal billet is used as the starting material. Rheocasting is a process in which material is cast in a mold while in a semi-liquid state, i.e., midway between its liquidus and solidus temperatures where it is partially liquid and partially solid. While at this temperature, the material is continuously stirred to keep all solid phases in suspension in the liquid. The process is capable of producing composites of materials that cannot otherwise be mixed together while one is in the liquid state. In this instance, the technique is being investigated for its potential as a low temperature, ferrous die casting process. The thixocasting process has potential application for a variety of vehicle and weapon components. A weapons component, a steel cartridge stop pawl (Figure 1), was selected as being the one most suitable for the investigation. The pawl is normally produced as a steel investment casting.

Figure 1 includes the specifications to which the pawls were supposed to conform under the contract. It also indicates some additional specifications to which the pawl would have to conform in production. The purpose of the investigation was to evaluate process feasibility, optimize variables, and evaluate process economics. The details of the results of the MIT investigation are given in a thesis by Boylan, which was supervised by Professor Merton C. Flemings.

#### MTL Work

The objective of the MTL investigation was to make an independent Government evaluation of the castings with respect to the contract specifications and other specifications applicable to the part in production. The results provide valuable technical background for any future development of the process.

# MATERIALS AND PROCEDURES

A lot consisting of eight pawls produced under the MIT study was selected for investigation. In addition, some castings made under slightly different conditions were taken outside this lot for chemical analysis and surface roughness measurement. These slight variations in thixocasting conditions would not affect the test results.

The thixocast steel was evaluated in the as-cast condition, with respect to the specifications, by visual and magnetic particle inspection, radiography, metallography, and chemical analysis. The pawls were then normalized at 1625°F for one hour in vacuum; austenitized at 1150°F for 30 minutes in air; oil quenched; and tempered at 850°F for one hour. Further evaluation was made by surface roughness test, dimensional measurement, hardness, and metallography.

<sup>1.</sup> BOYLAN, J.F. Machine Casting of a Low Alloy Steel Via the Thixocasting Processing. Master of Science Thesis, Massachusetts Institute of Technology, June 1978.

# RESULTS AND DISCUSSION

# As-Cast

SOUTH SECOND SECONDARY SECONDARY OF SECONDARY SECONDARY SECONDARY SECONDARY SECONDARY SECONDARY SECONDARY SECONDARY

Visual, Magnetic Particle, and Radiographic Examination

On visual examination, unacceptable cracks were seen. Magnetic particle inspection revealed unacceptable indications of severe cracking. Radiography showed unacceptable sponge and centerline shrink. The test results are summarized below.

Test	Result	Accept- ability	Applicable Specification
Visual (Figure 2)	Cracks present	No	MIL-W-13855
Magnetic Particle (Figure 3)	Indications of severe cracking	No	MIL-I-6868
Radio- graphy (Figure 4)	Sponge and centerline shrink	No	MIL-C-6021H

# Chemical Analysis

Chemical analysis of the steel was as follows:

Element (Wt.%)	Analyzed	Specification MIL-S-22141B
<u> </u>		<u> </u>
С	0.36-0.44	0.36-0.44
Mn	0.68-0.78	0.60-0.90
Si	0.25-0.29	0.20-0.80
Cr	0.76-0.81	0.70-0.90
Ni	1.70-1.74	1.65-2.00
Mo	0.23-0.25	0.20-0.30
P	0.008-0.009	0.025 max
S	0.014-0.023	0.025 max
A1	0.04-0.06	N/A
N (ppm)	130-200	300 typ.*
H (ppm)	3.1-5.6	10-20 typ.*
O (ppm)	480-1060	50 typ.*

<sup>\*</sup>Typical values obtained from Dr. Gordon A. Bruggeman, MTL, Watertown, MA

The analysis conformed to the specification. The aluminum analysis did not indicate that any great amount of the aluminum-bearing insulation used in thixocasting had become entrained. The nitrogen and hydrogen analyses appeared satisfactory. However, the oxygen analysis seemed rather high, possibly due to the entrainment of surface oxides.

# Metallographic Examination

Metallographic examination revealed the presence of shrinkage, hot tears, and gas porosity (Figures 5-9). The hot tearing occurred through the liquid, between the primary solid particles. The gas porosity may have resulted from air entrained during rheocasting or thixocasting. The cracks observed visually and by magnetic particle inspection were found to be surface cracks due to cooling, initiating at the surface and propagating through the prior liquid and around the primary solid particles (Figure 10). Cold shots and three phase inclusions were also present (Figure 11). These inclusions may consist of insulation from the lining of the die casting machine and/or entrained oxide. The prior liquid was grossly segregated from the primary solid (Figure 12).

The primary solid was mostly ferrite, and its microhardness converted to HRC 26. Areas to which carbon had segregated were mostly pearlite, and their converted hardness was HRC 44. Areas of even greater carbon segregation, composed primarily of martensite, had a converted hardness of HRC 59. The primary solid was ferrite and pearlite, and the prior liquid was pearlite and martensite, showing the segregation of martensite—stabilizing elements to the liquid (Figure 13). A particularly highly segregated area of the prior liquid was martensite, bainite and pearlite (Figure 14).

# Dimensions

The dimensions (see Figure 1) were as follows:

Dimension (in.)	Specified	Measured	Remarks
A	0.373-0.003	0.375-0.388	Unacceptable
В	0.343-0.013	0.343	Acceptable

Dimension "A" was in an area of shrinkage and gas porosity, which may have resulted in its unacceptably large measurement. Dimension "B" was in a relatively sound area, which resulted in an extraordinarily accurate measurement. If the problem of lack of soundness could be solved, the ability to cast accurate dimensions might be very valuable.

# Heat Treated

# Hardness

The hardness as heat treated ranged from below the HRC scale, in an area of porosity, up to 42.5 HRC. This was acceptable with respect to the 43-48 HRC specified.

# Surface Roughness

The surface roughness was 70-180 micro in. RMS. If the usual specification of 125 micro in. RMS had applied, this surface roughness would have been unacceptable.


#### Microstructure

THE PARTY OF THE P

In the microstructure, both low and high alloy tempered martensite were present after heat treatment, showing that the segregation produced by thixocasting persisted through thermal processing (Figure 15). Due to these defects and those noted above, before heat treatment, the structure was unacceptable on the basis of MIL-C-6021H.

# **CONCLUSIONS**

The thixocastings were unacceptable with respect to the specifications for Class 2 castings. The problems of shrinkage, hot tearing, gas porosity, cooling cracking, gross segregation, cold shots, inclusions, surface roughness, and dimensional control must be solved before the process can be considered for production.



#### Notes:

THE PERSON NAMED ASSESSED BANGES PROPERTY OF THE PARTY OF

- 1. Steel, composition IC 4340, MIL-S-22141B.
- 2. Classification and inspection shall be in accordance with Class 2, MIL-C-6021H.
- Heat treat per Spec. MIL-H-6875, quenched and tempered to 43 to 48 HRC.
- 4. The following notes would ordinarily apply, but not under the present contract:
  - a. Finish 125 micro in. RMS except as noted.
  - b. Inspect per MIL-I-6868.
  - c. MIL-W-13855 applies.
- 5. All dimensions in inches.

Figure 1. Pawl, cartridge stop.




Figure 2. Cracks observed by visual examination.



Figure 3. Magnetic particle indications of severe surface cracking.




Figure 4. Radiograph of casting No. 64. Unacceptable sponge and centerline shrink.



Spec. 64 -1



Spec 39-2

0.5 in.

Figure 5. Shrinkage, hot tears and gas porosity (both specimens).



Spec. 39-1

0.1 in.

Figure 6. Shrinkage cavity.



Spec. 64-2

0.1 in.

Figure 7. Hot tear.



Figure 8. Gas porosity.

0.01 in.



Spec. 64-2

0.001 in.

Figure 9. Hot tear through liquid and around primary solid.




Figure 10. Surface cooling crack through prior liquid and around primary solid.






Figure 11a. Cold shot.

0.01 in.




\_\_\_\_0.001 in.\_\_\_\_

Figure 11b. Three phase inclusion.



<mark>KAO</mark> PODOŽIVA (COSOSIOS PODOŽIVA) (COSOSIOS PODOŽIVA (COSOSIOS PODOŽIVA (COSOSIOS PODOŽIVA (COSOSIOS PODOŽIVA (C


Figure 12. Prior liquid segregated from primary solid.



0.001 in.

Figure 13a. Primary solid: ferrite and pearlite.

SOUND DESCRIPTIONS OF THE PROPERTY OF THE PROP



Spec. 64-1

LILLER ASSESSMENDER CONTRACTOR OF ASSESSMENT OF ASSESSMENT OF THE PROPERTY OF

0.001 in.

Figure 13b. Prior liquid: pearlite and martensite.



Spec. 64-1

CALLES - EXCESSION PROCESSION PROCESSION - Read

0.001 in.

Figure 14. Particularly highly segregated prior liquid area: martensite, bainite, and pearlite.




Figure 15. Low and high alloy martensite. Segregation persisting after heat treatment.

No. of Copies

To

1 Office of the Under Secretary of Defense for Research and Engineering, The Pentagon, Washington, DC 20301

Commander, U.S. Army Laboratory Command, 2800 Powder Mill Road, Adelphi, MD 20783-1145

1 ATTN: SLCIS-IM-TL

Commander, Defense Technical Information Center, Cameron Station, Building 5, 5010 Duke Street, Alexandria, VA 22304-6145

2 ATTN: DTIC-FDAC

1 Metals and Ceramics Information Center, Battelle Columbus Laboratories, 505 King Avenue, Columbus, OH 43201

Commander, Army Research Office, P.O. Box 12211, Research Triangle Park, NC 27709-2211

1 ATTN: Information Processing Office

Commander, U.S. Army Materiel Command, 5001 Eisenhower Avenue, Alexandria, VA 22333

1 ATTN: AMCLD

Commander, U.S. Army Materiel Systems Analysis Activity, Aberdeen Proving Ground, MD 21005

1 ATTN: AMXSY-MP, H. Cohen

Commander, U.S. Army Electronics Research and Development Command, Fort Monmouth, NJ 07703

1 ATTN: AMDSD-L

1 AMDSD-E

Commander, U.S. Army Missile Command, Redstone Scientific Information Center, Redstone Arsenal, AL 35898-5241

l ATTN: AMSMI-RKP, J. Wright, Bldg. 7574

1 AMSMI-RD-CS-R/ILL Open Lit

1 AMSMI-RLM

Commander, U.S. Army Armament, Munitions and Chemical Command, Dover, NJ 07801

2 ATTN: Technical Library

AMDAR-LCA, Mr. Harry E. Pebly, Jr., PLASTEC, Director

Commander, U.S. Army Natick Research, Development, and Engineering Center, Natick, MA 01760

1 ATTN: Technical Library

Commander, U.S. Army Satellite Communications Agency, Fort Monmouth, NJ 07703 1 ATTN: Technical Document Center

Commander, U.S. Army Tank-Automotive Command, Warren, MI 48090

1 ATTN: AMSTA-ZSK

2 AMSTA-TSL, Technical Library

XXXXXX

CONTRACTOR DESCRIPTION OF THE PROPERTY OF THE

Commander, White Sands Missile Range, NM 88002

1 ATTN: STEWS-WS-VT

President, Airborne, Electronics and Special Warfare Board, Fort Bragg, NC 28307

l ATTN: Library

Director, U.S. Army Ballistic Research Laboratory, Aberdeen Proving Ground, MD 21005

1 ATTN: AMDAR-TSB-S (STINFO)

Commander, Dugway Proving Ground, Dugway, UT 84022

1 ATTN: Technical Library, Technical Information Division

Commander, Harry Diamond Laboratories, 2800 Powder Mill Road, Adelphi, MD 20783

1 ATTN: Technical Information Office

Director, Benet Weapons Laboratory, LCWSL, USA AMCCOM, Watervliet, NY 12189

l ATTN: AMSMC-LCB-TL

1 AMSMC-LCB-R

1 AMSMC-LCB-RM

1 AMSMC-LCB-RP

Commander, U.S. Army Foreign Science and Technology Center, 220 7th Street, N.E., Charlottesville, VA 22901

l ATTN: Military Tech

Commander, U.S. Army Aeromedical Research Unit, P.O. Box 577, Fort Rucker, AL 36360

l ATTN: Technical Library

Director, Eustis Directorate, U.S. Army Air Mobility Research and Development Laboratory, Fort Eustis, VA 23604-5577

1 ATTN: SAVDL-E-MOS (AVSCOM)

U.S. Army Aviation Training Library, Fort Rucker, AL 36360

l ATTN: Building 5906-5907

Commander, U.S. Army Agency for Aviation Safety, Fort Rucker, AL 36362

l ATTN: Technical Library

Commander, USACDC Air Defense Agency, Fort Bliss, TX 79916

l ATTN: Technical Library

Commander, U.S. Army Engineer School, Fort Belvoir, VA 22060

l ATTN: Library

Commander, U.S. Army Engineer Waterways Experiment Station, P. O. Box 631, Vicksburg, MS 39180

1 ATTN: Research Center Library

Technical Director, Human Engineering Laboratories, Aberdeen Proving Ground, MD 21005

1 ATTN: Technical Reports Office

Commandant, U.S. Army Quartermaster School, Fort Lee, VA 23801

l ATTN: Quartermaster School Library

Naval Research Laboratory, Washington, DC 20375

1 ATTN: Dr. C. I. Chang - Code 5830

2 Dr. G. R. Yoder - Code 6384

Chief of Naval Research, Arlington, VA 22217

1 ATTN: Code 471

1 Edward J. Morrissey, AFWAL/MLTE, Wright-Patterson Air Force, Base, OH 45433

Commander, U.S. Air Force Wright Aeronautical Laboratories, Wright-Patterson Air Force Base, OH 45433

1 ATTN: AFWAL/MLC

1

THE STATE OF THE PROPERTY OF T

AFWAL/MLLP, M. Forney, Jr.

1 AFWAL/MLBC, Mr. Stanley Schulman

National Aeronautics and Space Administration, Marshall Space Flight Center, Huntsville, AL 35812

l ATTN: R. J. Schwinghammer, EHOl, Dir, M&P Lab

Mr. W. A. Wilson, EH41, Bldg. 4612

U.S. Department of Commerce, National Bureau of Standards, Gaithersburg, MD 20899

- 1 ATTN: Stephen M. Hsu, Chief, Ceramics Division, Institute for Materials Science and Engineering
- 1 Committee on Marine Structures, Marine Board, National Research Council, 2101 Constitution Ave., N.W., Washington, DC 20418
- 1 Librarian, Materials Sciences Corporation, Guynedd Plaza 11, Bethlehem Pike, Spring House, PA 19477
- 1 The Charles Stark Draper Laboratory, 68 Albany Street, Cambridge, MA 02139

Wyman-Gordon Company, Worcester, MA 01601

1 ATTN: Technical Library

Lockheed-Georgia Company, 86 South Cobb Drive, Marietta, GA 30063 1 ATTN: Materials and Processes Engineering Dept. 71-11, Zone 54

General Dynamics, Convair Aerospace Division, P.O. Box 748, Fort Worth, TX 76101

1 ATTN: Mfg. Engineering Technical Library

No. of		
110. 01		
Conica	To	
Copies	10	
•		

- 1 Mechanical Properties Data Center, Belfour Stulen Inc., 13917 W. Bay Shore Drive, Traverse City, MI 49684
- 1 Mr. R. J. Zentner, EAI Corporation, 198 Thomas Johnson Drive, Suite 16, Frederick, MD 21701
  - Director, U.S. Army Materials Technology Laboratory, Watertown, MA 02172-0001
- 2 ATTN: SLCMT-IML
- l Author

person the second of the secon

UNCLASSIFIED UNLIMITED DISTRIBUTION However, radiography revealed sponge and centerline shrink. Magnetic particle and visual inspection revealed severe surface cracking. Metallography showed not tears, yas porosity, cold shots, inclusions, and gross chemical segregation, resulting in incrostructural variation from ferrite to martensite, and hardness variation from 26 to 59 HKC. This segregation persisted through heat treatment. The surface hard-UNCLASSIFIED UNLIMITED DISTRIBUTION visual inspection revealed severe surface cracking. Metalloyraphy showed hot tears, yas porosity, cold shots, inclusions, and gross chemical segregation, resulting in alcrostructural variation from ferrite to martensite, and hardness variation from 26 to 59 HKL. Inis segregation persisted through heat treatment. The surface hardeight pawis was evaluated and found satisfactory with respect to chemical analysis. ness, roughness, and dimension did not conform to specifications, and the castings did not fulfill the specifications. The above defect problems must be resolved elylit pawls was evaluated and found satisfactory with respect to chemical analysis. Mbs machine gun in accordance with applicable specifications. A "lot" composed of Mas machine gun in accordance with applicable specifications. A "lot" composed of the objective of this work was to evaluate thixocast cartridge stop pawls for the The ubjective of this work was to evaluate thixocast cartridge stop pawls for the However, radioyraphy revealed sponge and centerline shrink. Maynetic particle and Key Words Key Words Microstructure Die casting Microstructure Steel casting Steel casting Die casting Ternoical Meport MTL TM 87-44, September 1987, 15 pp -111us, U/A Pruject 1L162105AH84 Technical Report MIL TR 87-44, September 1987, 15 pp illus, U/A Project 1L162105AH84 Watertown, Massachusetts 02172-0001 EVALUATION UF THIXOCAST CARTRIDGE STUP EVALUATION OF THIXOCAST CARTRIDGE STOP Army Materials Technology Laboratory, U.S. Army Materials Technology Laboratory, Watertown, Massachusetts 02172-0001 before the process can be utilized. Perry R. Smoot Perry R. Snoot PAMLS PAMLS .5.0 Jissai Insection revealed severe surface cracking. Metallography showed not tears, as purposity, cold snots, inclusions, and gross chemical segregation, resulting in inclusions and gross chemical segregation, resulting in the constitution from territe to martensite, and hardness variation from 26 to 29 mil.

This segregation persisted through heat treatment. The surface hardness, roughness, and dimension and not conform to specifications, and the castings and full fill the specifications. The above defect problems must be resolved. UNCLASSIFIED UNLIMITED DISTRIBUTION UNCLASSIFIED UNLIMITED DISTRIBUTION Metalloyraphy showed not tears, ancrostructural variation from ferrite to martensite, and hardness variation from 26 Ine ubjective of this work was to evaluate thixocast cartridge stop pawls for the Mobiliane you in accordance with applicable specifications. A "lot" composed of eight pawls was evaluated and found satisfactory with respect to chemical analysis. However, radiography revealed sponge and centerline shrink, Magnetic particle and the objective of this work was to evaluate thisocast cartridge stop pawls for the docidence with applicable specifications. A "lot" composed of elonby was evaluated and found satisfactory with respect to chemical analysis. sas porosity, cold shots, inclusions, and gross chemical segregation, resulting in to 59 mk. Inis segregation persisted through heat treatment. The surface hard-ness, roughness, and dimension did not conform to specifications, and the castings mowever, radio, raying revealed sponge and centerline shrink. Magnetic particle and did not fulfill the specifications. The above defect problems must be resolved Key Words Key Words Microstructure Microstructure Steel casting Steel casting Die casting Ole casting ą ð lechnical Report MTL TR 87-44, September 1987, 15 pp -illus, U/a Pruject IL162105AH84 Technical report MIL is 87-44, September 1987, 15 pp. 1516s, U.S. Project ittechosass visual inspection revealed severe surface cracking. Amny Materials Technology Laboratory, materiomn, Massachusetts U2172-0301 EALISTION OF THINOLAST CARTHIBLE STUP Anny Materials Technology Laboratory, Watertown, Massachusetts 02172-0001 EVALUATIUN UF THIXOCAST CARTRIDGE STOP before the process can be utilized. Perry K. Shout Perry R. Snoot ٠.১ *:* 

KKKKI ZEKROKIO EKKKKKIO EKKKKEIO EKKKEKO EKKEKEIO BEKKEKEIO EKKEKKIO BETTER BEKKKKKI BETTER BEKKKKKI DED

ness, roughness, and dimension did not conform to specifications, and the castings

did not fulfill the specifications.

before the process can be utilized.

before the process can be utilized.

The above defect problems must be resolved

END F b. 1988 DTIC